

GRINDEX Information

1997-01-30

TECHNICAL BULLETIN

TB 20

From: Tore Hovland, Technical Service Manager

Subject: New motor

Technical category: Electrical motor

Pump concerned: Senior

As the tool for manufacturing the stator lamination for the Senior motor is worn out, it has been necessary to change the motor for Senior.

Since the interchangeability is not complete, the product number has been changed from 76XX to 78XX.

	76XX	78XX
Rotor unit	5008800	5030900
Stator	50076XX	50308XX

The old rotor unit and the old stator will not be available as spare parts. A new motor fits in an old pump if **both stator and rotor unit** are changed.

