

Date:  
May 06, 2011

Technical Newsletter

No:  
36




[www.grindex.com](http://www.grindex.com)

Subject:  
Defect suction cover 132 423 for Maxi N

**Dear Distributor,**

During 2010/2011 there has been reports of poor bonding between rubber and metal on the suction cover 132 423, resulting in the rubber coming loose during operation. See picture below.



Since November 2010 the manufacturing problem has been solved. Defect components in local stock are detected by testing the bonding with pliers. If the bonding is defect the rubber will easily come off.

Please check your stock to prevent further pump failures, claim defect components according to standard procedure.

Yours sincerely,

*MagnusForssell*

Technical Support