

Date December 18, 2002	Technical Newsletter	No 3	GRINDEX
Subject Spare parts new bearing holders and spring support.			www.grindex.com

Dear Distributor,

In order to continue the product development program and day-to-day customer parts supply service efficiently, the following changes have been introduced:
 Old bearing holder Minex 130639 has been replaced by bearing holder 50 547 01 with a new spring support 50 594 00.
 Old bearing holder 140262 Minette/Salvador pumps has been replaced by bearing holder 50 546 01 with new spring support 50 594 00.

Pumps concerned: New Line Minex and Minette only.

Time of introduction:

From August 2002 when the stock of old bearing holders was running out.

Visual identification:

The new bearing holders have longer shoulder vanes for the spring support.
 The new spring support is made of machined stainless steel.

Parts interchangeability:

Old spring support 140083 does not fit new bearing holders.
 New spring support 5059400 fits new bearing holders only.
 On orders calling for bearing holder 130639 or 140262 the new holders with spring support will be supplied accordingly.

Yours faithfully

Sören Eriksson
 Technical Manager