

Date:
April 18, 2011

Technical Newsletter

No:
35



www.grindex.com

Subject:
VFD-drive

Dear Distributor,

Design modification

Most of the stators used in Minex-Master have no phase insulation which makes them unsuitable for VFD-drive. If a stator without phase insulation is run on VFD-drive, the life time of the stator will be reduced.

Stators with phase insulation are available on special order. Contact technical support for more information.

Note! Matador and bigger stators all have phase insulation and can be run on VFD.

Pumps concerned

Minex (8101.171) up to Master (8105.181) and Salvador (8109.281) up to Sandy (8111.280)

Yours sincerely,

Magnus Forssell

Technical Support