

Date:  
2016-04-07

Technical Newsletter

No:  
61



[www.grindex.com](http://www.grindex.com)

Subject:  
No air valve on Milli, 8125.230

### Background and explanation

The low suction pump Milli is based on the drainage pump Micro and share all main components and functions, except that Milli has no air valve on the pump top.

The reason to why Milli has no air valve is that when the pump has emptied all surrounding water and is snoring, the air valve would not close and then cause small amounts of water to continuously splash out through the air valve.

This would not look good in the eye of the customer, and since snoring is a very common duty point for Milli, there is no air valve on Milli.

Milli can still handle snoring and dry running continuously.



Yours sincerely,

*Per Nilsson*  
Technical Support